Unique Service Line ID	Site Name	Street Number	Street Name	City	Zip Code	County	Latitude	Longitude	In Asset Management	Asset Status	Asset Start Date	Asset End Date	System-Owned Portion Service Line Material Classification	If Non-Lead in Co	olumn O Service Line Installation	Is the Service Line Metered	Service Line Use	Service Line Size	Service Line Length
A Unique ID by the public water system for each service line.		Water systems must t	track addresses of all ser	vice lines in their interna	al inventory. For the public	cly accessible version, loc	ation identifiers are req	uired for lead and galv	anized requiring replacem ecify service line locations.	ent. If the system does	not use addresses for th	eir location identifier,	If "Non-Lead Other", describe in Comments field	Important for determining if service line requires replacement	Estimated date when the service line was installed or	Service Line Metered or Not Mettered	Drinking, Non- Drinking, Combination	Diameter in inches	Length in Feet
Example 1 (DO NOT DELETE)	Site Name	1234	Test St.	Test City	88888	Test County	an anno	-ar.arms	Yes, No, Unknown	Active, Inactive, Not	mm/dd/yyyy	mm/dd/yyyy	Non-Lead - Copper	Yes	replaced 3/19/1999	Yes	Drinking .	1.50	6
Example 2 (DO NOT DELETE)	House 1	1502	Main St	Braceville	44444	Adams	41.2566	-80.9806	No	Applicable Active	1/1/2022	1/1/2023	Non-Lead - Plastic	No	4/2/2005	Yes	Drinking	1.25	6
Example 3 (DO NOT DELETE)	Business 1	1268	Main St	Braceville	44444	Adams	41.2560	-80.9820	Yes	Inactive	1/15/2016		Non-Lead - Copper	No		Yes	Combination	2.50	8
AA	Alford Hall	200	N. Main St	Cedarville	45314	Greene	39.7460	-83.8083	Yes	Active	1/1/1926	ļ	Non-Lead - Plastic	Unknown	1/1/2015	No	Combination	1.50	150
APP	AppleTechnology Center	251	N. Main St	Cedarville	45314	Greene	39.7486	-83.8104	Yes	Active	1/1/1976	ļ	Non-Lead - Other	No	1/1/1976	No	Combination	1.50	249
APPF	AppleTechnology Center (fire)	251	N. Main St	Cedarville	45314	Greene	39.7486	-83.8104	Yes	Active	1/1/1976		Non-Lead - Other	No	1/1/1976	No	Non-Drinking	6	52
ATH	Athletic fields concession stand	251	N. Main St	Cedarville	45314	Greene	39.7561	-83.8158	Yes	Active	8/5/1998	ļ	Non-Lead - Copper	No	1/1/1998	No	Drinking	4	23
BDP1	Bates-Dunn-Parker Hall	251	N. Main St	Cedarville	45314	Greene	39.7524	-83.8155	Yes	Active	1/1/2020	ļ	Non-Lead - Other	No	1/1/2020	No	Combination	6	174
BRO	Brock Hall	251	N. Main St	Cedarville	45314	Greene	39.7536	-83.8124	Yes	Active	1/1/1989		Non-Lead - Other	No	1/1/1989	No	Combination	6	604
LIB	Centennial Library  Center for Biblical and Theological	251	N. Main St	Cedarville	45314	Greene	39.7483	-83.8118	Yes	Active	1/1/1987	ļ	Non-Lead - Other	No	1/1/1986	No	Combination	8	14
BTS	Studies Center for Biblical and Theological	251	N. Main St	Cedarville	45314	Greene	39.7491	-83.8110	Yes	Active	1/1/2008	ļ	Non-Lead - Other	No	1/1/2008	No	Combination	4	18
BTSF	Studies (fire)	251	N. Main St	Cedarville	45314	Greene	39.7491	-83.8110	Yes	Active	1/1/2008		Non-Lead - Other	No	1/1/2008	No	Non-Drinking	6	13
CLC	Chemistry Laboratory Center	251	N. Main St	Cedarville	45314	Greene	39.7465	-83.8135	Yes	Active	1/1/2015	ļ	Non-Lead - Other	No	1/1/2015	No	Combination	6	49
CFA	Chick-Fil-A	251	N. Main St	Cedarville	45314	Greene	39.748259	-83.811779	Yes	Active	1/1/2020	ļ	Non-Lead - Other	No	1/1/2020	No	Combination	6	10
CEC	Civil Engineering Center	251	N. Main St N. Main St	Cedarville Cedarville	45314 45314	Greene	39.746993 39.750352	-83.81345 -83.817026	Yes	Active Active	1/1/2020		Non-Lead - Other	No No	1/1/2020 1/1/2024	No No	Combination Combination	6 4	72
	Diehl-Johnson Phipps Murdoch	251	<del> </del>		<del> </del>	Greene			Yes			<del> </del>	Non-Lead - Other				<del> </del>	<del> </del>	63
DMC	Dixon Ministry Center	251	N. Main St	Cedarville	45314	Greene	39.75027	-83.812296	Yes	Active	1/1/1996	ļ	Non-Lead - Other	No	1/1/1996	No No	Combination	6	67
ENS	Engineering and Science Center	251	N. Main St	Cedarville	45314	Greene	39.747306	-83.813174	Yes	Active	1/1/1972	<del> </del>	Non-Lead - Other	No No	1/1/1992	No No	Combination	6	134
EPL ENGS	Engineering Projects Lab	251	N. Main St	Cedarville	45314	Greene	39.747053	-83.813368	Yes	Active	1/1/2005	<del> </del>	Non-Lead - Copper	No No	1/1/2005	No No	Combination	2	187
ENGS	Engineering storage	251	N. Main St	Cedarville	45314	Greene	39.745823	-83.813214	Yes	Active	9/1/2005	<del> </del>	Non-Lead - Copper	No	9/1/2005	No No	Combination	1.50	42
FTH FTRE	Faith Hall Fitness Recreation Center (fire)	240 251	N. Main St N. Main St	Cedarville Cedarville	45314 45314	Greene Greene	39.746602 39.750496	-83.808432 -83.8141498	Yes Yes	Active	1/1/1966	<del> </del>	Non-Lead - Copper Non-Lead - Other	Unknown	1/1/2015	No No	Combination Non-Drinking	6	50 88
FTR	Fitness Recreation Center	251	N. Main St	Cedarville	45314	Greene	39.750496	-83.8141498	Yes	Active	1/1/2003	ļ	Non-Lead - Other	No No	1/1/2003	No No	Combination	4	93
FH	Founders Hall	251	N. Main St	Cedarville	45314	Greene	39.746908	-83.809944	Yes	Active	1/1/2018		Non-Lead - Plastic	Unknown	1/1/2018	No	Combination	2	131
GTS	Graduate and Teaching Services	251	N. Main St	Cedarville	45314	Greene	39.746652	-83.810085	Yes	Active	1/1/1949	<del> </del>	Non-Lead - Plastic	Unknown	1/1/2001	No	Combination	1	245
GRO	Gromacki Hall	251	N. Main St	Cedarville	45314	Greene	39.752292	-83.817174	Yes	Active	1/1/2014		Non-Lead - Copper	No.	1/1/2014	No	Combination	2	7
OPSB	Grounds Barn	2840	Cedarville-	Cedarville	45314	Greene	39.74884	-83.820643	Yes	Active	1/1/2011		Non-Lead - Plastic	No	1/1/2011	No	Combination	2	80
HSC	Health Science Center	251	YellowSprings Rd. N. Main St	Cedarville	45314	Greene	39.747715	-83.815022	Yes	Active	1/1/2011	ł	Non-Lead - Other	No	1/1/2011	No	Combination	4	82
HSCF	Health Science Center (Fire)	251	N. Main St	Cedarville	45314	Greene	39.747715	-83.815022	Yes	Active	1/1/2011	ļ Ī	Non-Lead - Other	No	1/1/2011	No	Non-Drinking	6	72
HGC	History and Government Center	251	N. Main St	Cedarville	45314	Greene	39.74728	-83.8102	Yes	Active	1/1/1949		Non-Lead - Plastic	Unknown	1/1/2018	No	Combination	1	105
JKNS	Jenkins Hall	251	N. Main St	Cedarville	45314	Greene	39.751717	-83.816991	Yes	Active	1/1/2017		Non-Lead - Other	Unknown	1/1/2017	No	Combination	6	3
JNSN	Johnson Hall	251	N. Main St	Cedarville	45314	Greene	39.752808	-83.812572	Yes	Active	1/1/1999	İ	Non-Lead - Other	No	1/1/1999	No	Combination	6	41
LAWF	Lawlor Hall (fire)	251	N. Main St	Cedarville	45314	Greene	39.751521	-83.809982	Yes	Active	12/12/2008		Non-Lead - Other	No	12/12/2008	No	Non-Drinking	4	24
LAW	Lawlor Hall	251	N. Main St	Cedarville	45314	Greene	39.751521	-83.809982	Yes	Active	1/1/1979		Non-Lead - Other	No	1/1/2006	No	Combination	4	19
MX	Maddox Hall	303	N. Main St	Cedarville	45314	Greene	39.749933	-83.809558	Yes	Active	1/1/1967		Non-Lead - Other	No	1/1/1967	No	Combination	6	190
MXf	Maddox Hall (fire)	303	N. Main St	Cedarville	45314	Greene	39.749933	-83.809558	Yes	Active	5/22/2009	[	Non-Lead - Other	No	5/22/2009	No	Non-Drinking	6	37
MCCH	McChesney Hall	251	N. Main St	Cedarville	45314	Greene	39.752808	-83.812572	Yes	Active	1/1/1995		Non-Lead - Other	No	1/1/1995	No	Combination	6	54
MCKI	McKinney Hall	251	N. Main St	Cedarville	45314	Greene	39.752808	-83.812572	Yes	Active	1/1/1995	İ	Non-Lead - Other	No	1/1/1995	No	Combination	6	42
MIL	Milner Building	251	N. Main St	Cedarville	45314	Greene	39.74784	-83.81187	Yes	Active	1/1/1966		Non-Lead - Other	No	1/1/1966	No	Combination	3	194
MORT	Morton Hall	251	N. Main St	Cedarville	45314	Greene	39.752712	-83.813277	Yes	Active	1/1/2023	<u> </u>	Non-Lead - Other	No	1/1/2023	No	Combination	6	21
MPHY	Murphy Hall	251	N. Main St	Cedarville	45314	Greene	39.750389	-83.816418	Yes	Active	1/1/2002		Non-Lead - Other	No	1/1/2002	No	Combination	6	5
OPSC	Operations Center	2840	Cedarville- YellowSprings Rd.	Cedarville	45314	Greene	39.749631	-83.82034	Yes	Active	1/1/2016		Non-Lead - Copper	No	1/1/2016	No	Combination	2	12
PA	Palmer Hall	120	Church Street	Cedarville	45314	Greene	39.745282	-83.812295	Yes	Active	1/1/1999		Non-Lead - Other	Unknown	1/1/1999	No	Combination	1	72
BDP2	Parker Hall	251	N. Main St	Cedarville	45314	Greene	39.752014	-83.815496	Yes	Active	1/1/2020	ļ	Non-Lead - Other	No	1/1/2020	No	Combination	6	72
PAT	Patterson Hall	251	N. Main St	Cedarville	45314	Greene	39.747978	-83.80906	Yes	Active	1/1/1959		Non-Lead - Copper	No	1/1/1959	No	Combination	1.50	163
PRI	Printy	251	N. Main St	Cedarville	45314	Greene	39.750826	-83.811936	Yes	Active	1/1/1979	ļ	Non-Lead - Plastic	No	1/1/1979	No	Drinking	4	13
PRIF	Printy (fire)	251	N. Main St	Cedarville	45314	Greene	39.750826	-83.811936	Yes	Active	1/1/1979	ļ	Non-Lead - Other	No	1/1/1979	No	Non-Drinking	4	49
RICK	Rickard Hall	251	N. Main St	Cedarville	45314	Greene	39.750384	-83.816492	Yes	Active	1/1/2002		Non-Lead - Other	No	1/1/2002	No	Combination	6	30
RMC	The Hill	101	College Street	Cedarville	45314	Greene	39.745964	-83.81163	Yes	Active	1/1/2011		Non-Lead - Other	Unknown	6/22/2011	No	Combination	6	42
Rook	Rooke Hall Scharnberg Rusiness and	251	N. Main St	Cedarville	45314	Greene	39.752018	-83.817136	Yes	Active	1/1/2013	ļ	Non-Lead - Copper	No	1/1/2013	No	Combination	2	7
SBCC	Communication Cemter	251	N. Main St Cedarville-	Cedarville	45314	Greene	39.750496	-83.813624	Yes	Active	1/1/2024		Non-Lead - Other	No	1/1/2024	No	Combination	6	18
SHRB1	Shrubsole House	2912	YellowSprings Rd. Cedarville-	Cedarville	45314	Greene	39.747608	-83.816916	No	Inactive	7/1/2010	41275	Non-Lead - Plastic	No	1/1/2010	No	Drinking	2	1017
SHRB2	Shrubsole House	2912	YellowSprings Rd.	Cedarville	45314	Greene	39.747608	-83.816916	Yes	Active	1/1/2010	<b> </b>	Non-Lead - Other	Unknown	1/1/2013	No No	Combination	4	49
STCL	St. Clair Hall	251	N. Main St	Cedarville	45314	Greene	39.753524	-83.812348	Yes	Active	1/1/1999	ļ	Non-Lead - Other	No No	1/1/1999	No No	Combination	6	35
SSC SSCF	Stevens Student Center	346 346	Varsity Drive	Cedarville Cedarville	45314 45314	Greene Greene	39.749006 39.749006	-83.815745 -83.815745	Yes Yes	Active Active	1/1/2000	ļ	Non-Lead - Other	No No	1/1/2000	No No	Combination	4	109
SSCF TYL	Stevens Student Center (fire)  Tyler Digital Communication Center	346 251	Varsity Drive N. Main St	Cedarville Cedarville	45314 45314	Greene Greene	39.749006 39.74673	-83.815745 -83.81132	Yes Yes	Active	1/1/2000	<b> </b>	Non-Lead - Other  Non-Lead - Other	No Unknown	1/1/2000	No No	Non-Drinking Combination	6	109 182
WLK	Tyler Digital Communication Center  Walker Hall		i	j	45314 45314	ļi			<del> </del>	Active	1/1/1957	ļ		Unknown No	1/1/2002	No No	<b></b>	6	
WES	Walker Hall West Hall	251 251	N. Main St N. Main St	Cedarville Cedarville	45314 45314	Greene Greene	39.751386 39.750352	-83.816996 -83.817026	Yes Yes	Active	1/1/2018		Non-Lead - Other Non-Lead - Other	No No	1/1/2018	No No	Combination Combination	6	15 78
WES	West Hall Willets Hall Central (fire)	251	N. Main St N. Main St	Cedarville	45314 45314	Greene	39.750352 39.752444	-83.817026 -83.810239	Yes Yes	Active	1/1/2012	<del> </del>	Non-Lead - Other	No No	1/1/2012	No No	Non-Drinking	6	78 305
WILC	Willets Hall Central (fire)	251	N. Main St N. Main St	Cedarville	45314	Greene	39.752444	-83.810239	res Yes	Active	1/1/1982	<del> </del>	Non-Lead - Other	No No	1/1/2008	No No	Combination	4	305 58
WILN	Willets Hall North	251	N. Main St	Cedarville	45314	Greene	39.753053	-83.811126	Yes	Active	1/1/1982	<del> </del>	Non-Lead - Other	No	1/1/1993	No	Combination	6	124
WILS	Willets Hall South	251	N. Main St	Cedarville	45314	Greene	39.751771	-83.811281	Yes	Active	1/1/1993	<del> </del>	Non-Lead - Other	No	1/1/1992	No No	Combination	6	124
WI	Williams Hall	251	N. Main St	Cedarville	45314	Greene	39.74756	-83.81048	Yes	Active	1/1/1961		Non-Lead - Copper	Unknown	1/1/1961	No	Combination	1.50	226
WOOD	Wood Hall	251	N. Main St	Cedarville	45314	Greene	39.752651	-83.813708	Yes	Active	1/1/2022	<b> </b>	Non-Lead - Other	No	1/1/2022	No	Combination	6	96
L	1				L	ıi			نـــــن		L	4	L		L	L	L	1	

Basis of Material Classification			If Yes in Column W												
		Was the Service Line Material Field Verified?		Enter the Date of Field	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Service Line Length	Basis of Material Classification	Was the Service Line Material Field Verified?	If Yes in Colu		Connector Material Type	Is there Lead Solder in the Service Line?	
			Describe the Field Verification Method	Verification							Describe the Field Verification Method	Enter the Date of Field Verification			
Select option from d "Other," describe in			If Other, describe in the Notes field	Estimated date of field verification or date that the	If "Non-Lead Other", describe in Comments field	Estimated date when the service line was installed or replaced	Diameter in inches	Length in Feet	If Other, describe in the Notes field		If Other, describe in the Notes field	Estimated date of field verification or date that the record was updated	For example, lead gooseneck or pigtail where the water main is connected to the		
_				record was updated		·						·	service line		
Field inspection only  Previous Material		No			Lead	7/4/1905	1.25	6	Previous materials evaluation	Yes	Visual inspection at the meter pit	5/1/2019	Lead	No	
Previous Material  Installation record	(e.g., tap card)	Yes No	Visual inspection at meter pit	5/2/2019	Non-Lead - Copper Non-Lead - Plastic	7/12/1991 10/1/2001	2	9 12	Water sampling only with no records  Installation record (e.g., tap card)	No Yes	Customer self-identification	7/2/2017	Never Lead  Never Lead	No No	
Field inspection only	with no records	No	Visual inspection at meter pit		Non-Lead - Plastic	1/1/2015	1.50	150	Field inspection only with no records	No	Visual inspection at meter pit		Unknown	Unknown	
Field inspection only	with no records	No	Visual inspection at meter pit		Non-Lead - Other	1/1/1976	1.50	249	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	Unknown	
Field inspection only	with no records	No	Visual inspection at meter pit		Non-Lead - Other	1/1/1976	6	52	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
Field inspection only	with no records	No	Visual inspection at meter pit		Non-Lead - Copper	1/1/1998	4	23	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
Field inspection only	with no records	No	Visual inspection at meter pit	<u> </u>	Non-Lead - Other	1/1/2020	6.00	174	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
Field inspection only	with no records	No	Visual inspection at meter pit		Non-Lead - Other	1/1/1989	6	604	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
Field inspection only	with no records	No	Visual inspection at meter pit		Non-Lead - Other	1/1/1986	8	14	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
Field inspection only	with no records	No	Visual inspection at meter pit		Non-Lead - Other	1/1/2008	4	18	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
Field inspection only	with no records	No	Visual inspection at meter pit	İ	Non-Lead - Other	1/1/2008	6	13	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
Field inspection only		Yes	Mechanical Excavation at 1 location	3/4/2015	Non-Lead - Other	1/1/2015	6	49	Field inspection only with no records	Yes	Mechanical Excavation at 1 location	3/4/2015	Never Lead	No	
Field inspection only		Yes	Mechanical Excavation at 1 location	9/26/2019	Non-Lead - Other	1/1/2020	6	10	Field inspection only with no records	Yes	Mechanical Excavation at 1 location	9/26/2019	Never Lead	No	
Field inspection only		Yes	Mechanical Excavation at 1 location	11/13/2019	Non-Lead - Other	1/1/2020	6	72	Field inspection only with no records	Yes	Mechanical Excavation at 1 location	11/13/2019	Never Lead	No	
ļ			Ļ	11/15/2015		ļ				· <del> </del>		11/13/2019	ļ	ļ	
Field inspection only		No	Visual inspection at meter pit		Non-Lead - Other	1/1/2024	4	63	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
Field inspection only		No	Visual inspection at meter pit	ļ	Non-Lead - Other	1/1/1996	6	67	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
Field inspection only		No	Visual inspection at meter pit		Non-Lead - Other	1/1/1992	6	134	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
Field inspection only		Yes	Mechanical Excavation at 1 location	3/22/2005	Non-Lead - Copper	1/1/2005	2	187	Field inspection only with no records	Yes	Mechanical Excavation at 1 location	3/22/2005	Never Lead	No	
Field inspection only		No	Visual inspection at meter pit	ļ 	Non-Lead - Copper	9/1/2005	1.50	42	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
Field inspection only		No	Visual inspection at meter pit	ļ	Non-Lead - Copper	1/1/2015	2	50	Field inspection only with no records	No	Visual inspection at meter pit		Unknown	Unknown	
Field inspection only		No	Visual inspection at meter pit		Non-Lead - Other	1/1/2003	6	88	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
Field inspection only	with no records	No	Visual inspection at meter pit	<u> </u>	Non-Lead - Other	1/1/2003	4	93	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
Field inspection only	with no records	Yes	Mechanical Excavation at 1 location	6/1/2018	Non-Lead - Plastic	1/1/2018	2	131	Field inspection only with no records	Yes	Mechanical Excavation at 1 location	6/1/2018	Never Lead	No	
Field inspection only	with no records	No	Visual inspection at meter pit		Non-Lead - Plastic	1/1/2001	1	245	Field inspection only with no records	No	Visual inspection at meter pit		Unknown	Unknown	
Field inspection only	with no records	Yes	Mechanical Excavation at 1 location	5/16/2014	Non-Lead - Copper	1/1/2014	2	7	Field inspection only with no records	Yes	Mechanical Excavation at 1 location	5/16/2014	Never Lead	No	
Field inspection only	with no records	No	Visual inspection at meter pit		Non-Lead - Plastic	1/1/2011	2	80	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
Field inspection only	with no records	Yes	Mechanical Excavation at 1 location	4/8/2011	Non-Lead - Other	1/1/2011	4	82	Field inspection only with no records	Yes	Mechanical Excavation at 1 location	4/8/2011	Never Lead	No	
Field inspection only	with no records	Yes	Mechanical Excavation at 1 location	4/8/2011	Non-Lead - Other	1/1/2011	6	72	Field inspection only with no records	Yes	Mechanical Excavation at 1 location	4/8/2011	Never Lead	No	
Field inspection only	with no records	No	Visual inspection at meter pit		Non-Lead - Plastic	1/1/2018	1	105	Field inspection only with no records	No	Visual inspection at meter pit		Unknown	Unknown	
Field inspection only	with no records	Yes	Mechanical Excavation at 1 location	12/23/2016	Non-Lead - Other	1/1/2017	6	3	Field inspection only with no records	Yes	Mechanical Excavation at 1 location	12/23/2016	Never Lead	No	
Field inspection only	with no records	No	Visual inspection at meter pit		Non-Lead - Other	1/1/1999	6	41	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
Field inspection only	with no records	Yes	Mechanical Excavation at 1 location	12/12/2008	Non-Lead - Other	12/12/2008	4.00	24	Field inspection only with no records	Yes	Mechanical Excavation at 1 location	12/12/2008	Never Lead	No	
Field inspection only		No	Visual inspection at meter pit	,,	Non-Lead - Other	1/1/2006	4	19	Field inspection only with no records	No	Visual inspection at meter pit	,,	Never Lead	No	
Field inspection only		No	Visual inspection at meter pit		Non-Lead - Other	1/1/1967	6	190	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
Field inspection only		No	Visual inspection at meter pit  Visual inspection at meter pit		Non-Lead - Other	5/22/2009	6	37	Field inspection only with no records	No.	Visual inspection at meter pit  Visual inspection at meter pit		Never Lead	No.	
Field inspection only		No	Visual inspection at meter pit  Visual inspection at meter pit	ļ	Non-Lead - Other	1/1/1995	6	54	Field inspection only with no records	No	Visual inspection at meter pit	<u> </u>	Never Lead	No No	
		+								<del> </del>			<b>+</b>	ļ	
Field inspection only		No	Visual inspection at meter pit	ļ	Non-Lead - Other	1/1/1995	6	42	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
Field inspection only		No	Visual inspection at meter pit	ļ	Non-Lead - Other	1/1/1966	3	194	Field inspection only with no records	No	Visual inspection at meter pit		Unknown	Unknown	
Field inspection only		No	Visual inspection at meter pit		Non-Lead - Other	1/1/2023	6	21	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
Field inspection only	with no records	No	Visual inspection at meter pit		Non-Lead - Other	1/1/2002	6	5	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
Field inspection only	with no records	Yes	Mechanical Excavation at 1 location	4/13/2016	Non-Lead - Copper	1/1/2016	2	12	Field inspection only with no records	Yes	Mechanical Excavation at 1 location	4/13/2016	Never Lead	No	
Field inspection only	with no records	No	Visual inspection at meter pit	ļ	Non-Lead - Other	1/1/1999	1	72	Field inspection only with no records	No	Visual inspection at meter pit		Unknown	Unknown	
Field inspection only	with no records	No	Visual inspection at meter pit	ļ	Non-Lead - Other	1/1/2020	6	72	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
Field inspection only	with no records	No	Visual inspection at meter pit		Non-Lead - Copper	1/1/1959	1.50	163	Field inspection only with no records	No	Visual inspection at meter pit		Unknown	Unknown	
Field inspection only	with no records	No	Visual inspection at meter pit		Non-Lead - Plastic	1/1/1979	4	13	Field inspection only with no records	No	Visual inspection at meter pit		Unknown	Unknown	
Field inspection only	with no records	No	Visual inspection at meter pit		Non-Lead - Other	1/1/1979	4	49	Field inspection only with no records	No	Visual inspection at meter pit		Unknown	Unknown	
Field inspection only	with no records	No	Visual inspection at meter pit		Non-Lead - Other	1/1/2002	6	30	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
Field inspection only	with no records	Yes	Mechanical Excavation at 1 location	6/1/2011	Non-Lead - Other	6/22/2011	6	42	Field inspection only with no records	Yes	Mechanical Excavation at 1 location	6/1/2011	Unknown	Unknown	
Field inspection only	with no records	No	Visual inspection at meter pit		Non-Lead - Copper	1/1/2013	2	7	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
Field inspection only	with no records	No	Visual inspection at meter pit		Non-Lead - Other	1/1/2024	6	18	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
Field inspection only	with no records	No	Visual inspection at meter pit	İ	Non-Lead - Plastic	1/1/2010	2.00	1017	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
Field inspection only	with no records	No	Visual inspection at meter pit		Non-Lead - Other	1/1/2013	4	49	Field inspection only with no records	No	Visual inspection at meter pit		Unknown	Unknown	
Field inspection only	with no records	No	Visual inspection at meter pit		Non-Lead - Other	1/1/1999	6	35	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
Field inspection only		No	Visual inspection at meter pit	ļ	Non-Lead - Other	1/1/2000	4	109	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No No	
Field inspection only		No	Visual inspection at meter pit	<del> </del>	Non-Lead - Other	1/1/2000	6	109	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No No	
Field inspection only		No	Visual inspection at meter pit  Visual inspection at meter pit		Non-Lead - Other	1/1/2002	6	182	Field inspection only with no records	No No	Visual inspection at meter pit  Visual inspection at meter pit		Unknown	No No	
		. <del> </del>				L	ii			ļ				i	
Field inspection only		No	Visual inspection at meter pit	<b> </b>	Non-Lead - Other	1/1/2018	6	15	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
Field inspection only	with no records	No	Visual inspection at meter pit	ļ	Non-Lead - Other	1/1/2012	6	78	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
			Visual inspection at meter pit		Non-Lead - Other	1/1/2008	6	305	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	
ļ	with no records	No	Ļ	<del> </del>		!									
Field inspection only	with no records	No	Visual inspection at meter pit		Non-Lead - Other	1/1/1992	4	58	Field inspection only with no records	No	Visual inspection at meter pit		Unknown	Unknown	
ļ	with no records		Ļ		Non-Lead - Other Non-Lead - Other	1/1/1993	6	58 124	Field inspection only with no records  Field inspection only with no records	No No	Visual inspection at meter pit  Visual inspection at meter pit		Unknown Never Lead	Unknown No	
Field inspection only	with no records	No	Visual inspection at meter pit												
Field inspection only Field inspection only	with no records with no records with no records	No No	Visual inspection at meter pit Visual inspection at meter pit		Non-Lead - Other	1/1/1993	6	124	Field inspection only with no records	No	Visual inspection at meter pit		Never Lead	No	

Building Type Connected to Service Line	If Column AJ includes a school	Building Construction Date	Building Plumbing Materials	Plumbing installation/replacement	Point-of-Entry or Point- of-Use Treatment	LCR Sampling Point ID	Date of System-	Date of Customer-	
	Lowest Grade Served	Date		date	Present?	ΙŪ	owned LSLR	owned LSLR	
	This info	ormation may be helpful for ic	dentifying lead tap monitoring location	15.					Please use this section to record any comments or notes associated with a service line.
	i								
Single Family Structure		6/1/1968	Galvanized	6/1/1968	Yes	LC201			
Single Family Structure with Childcare Facility  Non-Residential Building	i I	2/16/2019 10/1/2001	Copper with Lead Solder Non-Lead- Plastic	7/15/2015	Yes No			ļ	
Non-Residential Building		1/1/1853	Unknown - Material Unknown	1/1/1926	No				
Non-Residential Building		1/1/1976	Non-Lead - Other	1/1/1976	No				
Non-Residential Building		1/1/1976	Non-Lead - Other	1/1/1976	No				
Non-Residential Building	İ	1/1/1998	Non-Lead- Copper	1/1/1998	No	LC208			
Multi-Family Residence	İ	1/1/2020	Non-Lead- Copper	1/1/2020	No			ļ	
Multi-Family Residence		1/1/1989	Non-Lead- Copper	1/1/1989	No				
Non-Residential Building		1/1/1987	Non-Lead-Copper	1/1/1987	No				
Non-Residential Building		1/1/2008	Non-Lead- Copper	1/1/2008	No	LC214			
Non-Residential Building		1/1/2008	Non-Lead - Other	1/1/2008	No			ļ	
Non-Residential Building		1/1/2015	Non-Lead-Copper	1/1/2015	No				
Non-Residential Building	<u> </u>	1/1/2020	Non-Lead-Copper	1/1/2020	Yes			ļ	
Non-Residential Building		1/1/2020	Non-Lead-Copper	1/1/2020	No				
Multi-Family Residence	ļ	1/1/2024	Non-Lead- Copper	1/1/2024	No.			ļ	
		<b>↓</b>		ļ	ļ				
Non-Residential Building		1/1/1996	Non-Lead- Copper	1/1/1996	No	LC212		ļ	
Non-Residential Building		1/1/1972	Unknown - Material Unknown	1/1/1993	No	LC209		ļ	
Non-Residential Building		1/1/2005	Non-Lead-Copper	3/22/2005	No			ļ	
Non-Residential Building	ļ 	6/1/2005	Non-Lead- Copper	9/1/2005	No			ļ	
Multi-Family Residence		1/1/1966	Copper with Lead Solder	1/1/1966	No			ļ	
Non-Residential Building		1/1/2003	Non-Lead - Other	1/1/2003	No				
Non-Residential Building		1/1/2003	Non-Lead- Copper	1/1/2003	No	LC213		ļ	
Non-Residential Building		1/1/1895	Unknown - Material Unknown	3/7/2001	No	LC211			
Non-Residential Building		1/1/1949	Non-Lead- Copper	12/5/2001	No				
Multi-Family Residence		1/1/2014	Non-Lead- Copper	1/1/2014	No				
Non-Residential Building		1/1/2011	Non-Lead- Copper	1/1/2016	No				
Non-Residential Building		1/1/2011	Non-Lead-Copper	1/1/2011	No	LC218			
Non-Residential Building		1/1/2011	Non-Lead - Other	1/1/2011	No				
Non-Residential Building		1/1/1949	Non-Lead- Copper	1/1/1949	No	LC203			
Multi-Family Residence		1/1/2017	Non-Lead- Copper	1/1/2017	No				
Multi-Family Residence		1/1/1999	Non-Lead- Copper	1/1/1999	No	LC216		ļ	
Multi-Family Residence		1/1/1979	Non-Lead - Other	12/12/2008	No				
Multi-Family Residence		1/1/1979	Copper with Lead Solder	1/1/1979	No	LC207		ļ	
Multi-Family Residence		1/1/1967	Copper with Lead Solder	1/1/1967	No	LC219			
Multi-Family Residence		1/1/1967	Non-Lead - Other	5/22/2009	No			<del> </del>	
Multi-Family Residence		1/1/1995	Non-Lead- Copper	1/1/1995	No	LC215		<del> </del>	
Multi-Family Residence	<del> </del>	1/1/1995	Non-Lead- Copper	1/1/1995	No	1013		<b></b>	
Multi-Family Residence		1/1/1993	Copper with Lead Solder	1/1/1966	No	LC205		<del> </del>	
Multi-Family Residence	ļ	1/1/2023	Non-Lead-Copper	1/1/2023	No No	10205		ļ	
	<u> </u>				<del> </del>				
Multi-Family Residence	ļ	1/1/2002	Non-Lead- Copper	1/1/2002	No			ļ	
Non-Residential Building		1/1/2016	Non-Lead- Copper	1/1/2016	No	LC201		ļ	
Multi-Family Residence	ļ	1/1/1964	Non-Lead- Copper	1/1/1999	No			ļ	
Multi-Family Residence		1/1/2020	Non-Lead- Copper	1/1/2020	No			ļ	
Non-Residential Building		1/1/1959	Copper with Lead Solder	1/1/1959	No	LC217			
Multi-Family Residence	ļ	1/1/1979	Copper with Lead Solder	1/1/1979	No	LC206		ļ	
Multi-Family Residence	ļ	1/1/1979	Non-Lead - Other	1/1/2007	No			ļ	
Multi-Family Residence		1/1/2002	Non-Lead- Copper	1/1/2002	No				
Multi-Family Residence		1/1/1967	Non-Lead- Copper	1/1/2012	No	LC220			
Multi-Family Residence		1/1/2014	Non-Lead- Copper	1/1/2014	No				
Non-Residential Building		1/1/2024	Non-Lead - Other	1/1/2024	No				
Multi-Family Residence		1/1/1950	Unknown - Material Unknown	1/1/1950	No				
Multi-Family Residence		1/1/1950	Unknown - Material Unknown	1/1/2013	No				
Multi-Family Residence		1/1/1999	Non-Lead- Copper	1/1/1999	No			[	
Non-Residential Building		1/1/2000	Non-Lead- Copper	1/1/2000	Yes	LC210			
Non-Residential Building		1/1/2000	Non-Lead - Other	1/1/2000	No		l		
Non-Residential Building		1/1/1957	Non-Lead- Copper	1/1/2002	No		l	!	
Multi-Family Residence		1/1/2018	Non-Lead- Copper	1/1/2018	No			†	
Multi-Family Residence		1/1/2012	Non-Lead- Copper	1/1/2012	No				
Multi-Family Residence		1/1/1982	Non-Lead - Other	1/1/2008	No			†	
Multi-Family Residence		1/1/1982	Unknown - Material Unknown	1/1/1982	No	LC202			
Multi-Family Residence		1/1/1993	Non-Lead- Copper	1/1/1993	No No			<b></b>	
Multi-Family Residence		1/1/1993	Non-Lead- Copper	1/1/1992	No			<del> </del>	
Multi-Family Residence		1/1/1992	Unknown - Material Unknown	1/1/1992	No No			ļ	
Multi-Family Residence		1/1/1961	Non-Lead- Copper	1/1/1961	No No				
wurti-Hamily Residence	i	1/1/2022	Non-Lead- Copper	1/1/2022	NO		L	L	